

Référence	4JFHG X
Désignation	Q& à æ^ Á Áé ãæã } Á àãæ^ À Ò €€Ô

Anomalie :

✓ Û ã^ Á æ } ^ Á Áæ | ^ { ã+^ Á çã æã } É.]. ææã } & [] | - Á æã Á [^ • Á ææ ç Á æ Á Áæã | ææ ç&ã ã ç áæ] [| :Á



SERVICE REPORT

Ticket No.: 10209

Work Order No.: 1208751

Date: 04/10/2023

Page: 1 of 1

Ship to: 20 20067118

DOMINIQUE DUTSCHER
2 C RUE DE BRUXELLES
67170 BERNOLSHEIM 67170 FR

Attention:

Customer Reference:

Service: WARRANTY REPAIR

Item repaired is warranted to the end of the warranty period or for 3 months from date of dispatch whichever is the longer.

Product: 79520-22 - SI600C SI600 WITH COOLER

Serial number: R000100218

Reported fault: The belt is OK, but if we try to put the shaking ON, it does not work. If we help the instrument by hand, it works but if we select a high speed the instrument makes a lot of noise or is not able to shake. You can see at the attached video "noise shaking".

Problem: Bearing failure.

Resolution: All bearings replaced. New belt access panel installed. Service mechanism modifications done. Spare Belts Included.

Notes:

SAV 3948144