PFENNIG
REINIGUNGSTECHNIK

Workflow

MopScoop®



STEP 1: Press the trigger in the tray using the mop frame. Liquid is automatically pre-dosed.



STEP 2: Open the mop frame without touching it.



STEP 3: Pick up the mop without touching it.



STEP 4: Press the trigger in the tray using the mop frame while simultaneously picking up liquid with the mop. The liquid is pre-dosed again by lifting the mop frame.



STEP 5: Carry out the wiping process.



STEP 6: Drop the mop without touching it and repeat STEP 3 to 6.

DOMINIQUE DURSCHER

You can find more workflows in our downloads:

pfennig-reinigungstechnik.com/en/service/downloads

The Home of Clean