

TECHNICAL SPECIFICATIONS

Trade name	Sterilisation indicator tape
Use	Adhesive tape to indicate dry method (PUPINEL method) sterilization. To be used with individual units (i.e. packs, containers) to demonstrate that the unit has been exposed to the sterilization treatment and to distinguish between processed and unprocessed units. NOT INTENDED FOR USE AS VALIDATION SYSTEM OF STERILIZATION PROCESS
Material (backing)	Impregnated semicreped and printed paper
Type of adhesive	Silicone
Change that occurs after sterilization	Colour of the light green "V" becomes brown
Minimum conditions for change	Dry method 30 minutes at 155 ° C

**DIMENSIONAL SPECIFICATIONS**

Total thickness	mm. 0,15
Tensile strength	7,5%

GENERAL FEATURES

CE Mark	No
Conformity	ISO 11140-1:2015
Product classification	Indicators Class 1
Storage conditions	Temperature between 15 and 30°C – relative humidity between 30 and 70%
Storage time	36 months

PACKAGING

Case	48 pcs single wrapped
------	-----------------------

Quality Assurance