

Important information re: MSDS for

GenTegra® RNA, GTR100-B, 2.0 ml Screw Cap Tubes Dry BULK; and 5.0mL screw cap tube GenTegraRNA dry BULK, GTR100-B5.

Per OSHA 29CFR1910.1200, Commonwealth of Australia [NOHSC:1005, 1008(1999)] and the latest amendments to the European Union Directives 67/548/EC and 1999/45/EC, Part 3 of Annex VI to Regulation (EC) No 1272/2008, the products (GenTegra™ RNA 0.5ml Cluster Tubes, 0.5 ml Screw Cap Tubes, 96-well microplates and 1.5ml Screw Cap Tubes, 2.0 ml Screw Cap Tube Dry BULK, and 5.0mL screw cap tube Dry BULK, GTR100-B5) do not require a Material Safety Data Sheet (MSDS). The products do not contain more than 1% of a component classified as hazardous and do not contain more than 0.1% of a component classified as carcinogenic. Therefore, GenTegra does not provide an MSDS for these products.

It is highly recommended; however, when working with these products that good laboratory practice is followed. This includes the use of gloves, lab coats, and eye protection. General laboratory protective and hygienic measures should be taken. Examples include keeping foodstuffs and beverages away from the laboratory, washing hands before breaks and at the end of work, and minimizing opportunities for spills, trips or falls. GenTegra assumes no liability for damage resulting from improper handling or contact with these products.

For additional information on the hazards of this product, appropriate emergency procedures, or for technical support, please contact GenTegra Technical Support at 1-925-461-3010 or www.gentegra.com.